




Adapter Tube Required
(1-6015 or 1-6218 suggested)



Adapter Tube Required
(1-6015 or 1-6218 suggested)



- 2-50025 M26 x 36 TPI
- 2-50026 0.800 x 36 RMS
- 2-51370 M25 x 0.75

- | | | |
|-------------|-------------|-------------|
| Mitutoyo | Motic | Navitar HR |
| 1-60226 5X | 1-62828 5X | 1-55075 4X |
| 1-60227 10X | 1-62829 10X | 1-55401 6X |
| 1-60228 20X | 1-62830 20X | 1-55227 10X |
| 1-60229 50X | | |

- 2-50145 1X Converter Lens
- 1-50012 0.5X
- 1-50013 0.75X
- 1-50014 1.5X
- 1-50015 2X

Note: Factory alignment
of all parts is required.